

GREGORY S. BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals	Inspection	Report

Reviewed

	Rep	oort Date: 11/13/201	13		
Mine Name: Maynard Topaz		Permit Number:	S/023/0099	Mine Status:	Inactive
Oper	ator Name: : Colorado Calumet Co. Inc	Inspection Date:	08/22/2013	Permit Fees:	Paid
Inspector(s): Paul Baker and Wayne Western Inspection			9:15-9:30 AM	Bond Amount:	\$4,000
Atter	ndee(s):	Weather:	50s, mostly cloud	dy Bond Escalation:	08/04/2013
Inspection Purpose: Operator requested bond release				Prior Inspection:	08/26/2013
Conc	clusions and Recommendations getation is adequate, and the remaining surety show	ıld be released.			
Elements of Inspection			E	valuated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds				П
2. Public Safety (shafts, adits, trash, signs, highwalls)					
3. Protection of Drainages/Erosion Control					
4.					
5. Roads (maintenance, surfacing, dust control, safety)					
6.	Reclamation				
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)					
8.	Soils				
9.	Revegetation			\boxtimes	
	After driving miles over halogeton, Russian thist the vegetation is fourwing saltbush, forage kochia probably either bluebuch wheatgrass or slender w sagebrush, probably Wyoming big sage. I did not disturbed area was clearly at least 70 percent of the disturbed area have less vegetation than others, but are plants growing even in those areas that appear	i, Indian ricegrass, and a per heatgrass. The vegetation of think it was necessary to take the cover in undisturbed area at I was impressed with two	rennial bunchgrass community in surro ake vegetation covers. As can be seen	which I did not try to id bunding areas was domin er measurements because in the photos, some parts	entify. It is nated by e cover in the s of the
10.	Other				

Inspector's Signature:

CC: Jerry Mansfield, SITLA

 $File: \ / nrwogmfs 1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230099-Maynard Topaz/inspections/Insp11132013.pdf$



Mine: S/023/0099 Inspected: 08/22/2013



The photos are all overviews of the reclaimed area.







